

TOTAL PERFORMANCE
VAN'S AIRCRAFT

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

SERVICE BULLETIN 15-03-05

Date Released: March 5, 2015

Date Effective: March 5, 2015

Subject: Rotax carb float exchange

Affected Models: All RV-12 aircraft using ROTAX 912 ULS engines from S/N 678 0228 up to 678 3917

For float part number and carburetor part numbers and serial numbers refer to:

ROTAX Service Bulletin SB-912-067UL

Required Action: Refer to the ROTAX Service Bulletin shown above

Time of Compliance: Refer to the ROTAX Service Bulletin shown above

Supercedes Notice: SB 14-10-14

Labor Required: Estimate 2.0 Hours to remove and replace floats.
SLSA Warranty Allowance: N/A

Level of Certification: LSA Repairman Maintenance or A&P

Synopsis: Refer to the ROTAX Service Bulletin shown above

Method of Compliance: Refer to the ROTAX Service Bulletin shown above