

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

SERVICE BULLETIN 17-10-14

Date Released: October 14, 2017

Date Effective: October 14, 2017

Subject: Rotax SB-912-070

https://legacy.rotaxowner.com/si_tb_info/serviceb/sb-912-070.pdf https://legacy.rotaxowner.com/si_tb_info/serviceb/sb-912-070ul.pdf

Affected Models: All RV-12 aircraft using ROTAX 912 ULS engines

from S/N 6 785 971 up to S/N 6 786 198 inclusive from S/N 6 786 501 up to S/N 6 787 000 inclusive from S/N 9 569 001 up to S/N 9 569 690 inclusive from S/N 9 569 693 up to S/N 9 569 702 inclusive

S/N 9 569 823

Required Action: Refer to the ROTAX Service Bulletin shown above

Time of Compliance: Refer to the ROTAX Service Bulletin shown above

Labor Required: Estimate 1.5 Hours for inspection **SLSA Warranty Allowance:** N/A – refer to Rotax documentation

Level of Certification: LSA Repairman Maintenance or A&P

Synopsis: Refer to the ROTAX Service Bulletin shown above

Method of Compliance: Refer to the ROTAX Service Bulletin shown above