

SERVICE BULLETIN 19-07-29

Date Released: July 29, 2019

Date Effective: July 29, 2019

Subject: Rotax SB-912-073 UL

Affected Models: All RV-12 and RV-12iS aircraft using ROTAX 912 ULS engines

from S/N 6 784 306 up to S/N 6 787 000 inclusive from S/N 9 565 001 up to S/N 9 573 266 inclusive from S/N 9 573 268 up to S/N 9 573 271 inclusive

Affected Serial Numbers: All RV-12 and RV-12iS model aircraft

Required Action: Refer to ROTAX Service Bulletin shown above

Time of Compliance: Refer to ROTAX Service Bulletin shown above

Labor Required: Estimate 1.3 Hours

SLSA Warranty Allowance: N/A – refer to ROTAX documentation

Level of Certification: Refer to ROTAX Service Bulletin shown above

Synopsis: Refer to ROTAX Service Bulletin shown above

Materials Required: Refer to ROTAX Service Bulletin shown above

Method of Compliance: Refer to ROTAX Service Bulletin shown above