

**TOTAL PERFORMANCE**  
**VAN'S AIRCRAFT**

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • [www.vansaircraft.com](http://www.vansaircraft.com) • [info@vansaircraft.com](mailto:info@vansaircraft.com)

Service Letters and Bulletins: [www.vansaircraft.com/public/service.htm](http://www.vansaircraft.com/public/service.htm)

## **SERVICE BULLETIN 14-10-14**

**Date Released:** October 14, 2014

**Date Effective:** October 14, 2014

**Subject:** Periodic inspection of the float buoyancy

**Affected Models:** All RV-12 aircraft using ROTAX 912 ULS engines from S/N 6 780 228.

For float part number and carburetor part numbers and serial numbers refer to:

### **ROTAX Service Bulletin SB-912-065UL**

**Required Action:** Refer to the ROTAX Service Bulletin shown above

**Time of Compliance:** Refer to the ROTAX Service Bulletin shown above

**Synopsis:** Refer to the ROTAX Service Bulletin shown above

**Method of Compliance:** Refer to the ROTAX Service Bulletin shown above

**Labor Required:** Estimate 2.0 Hours to perform test.

**SLSA Warranty Allowance:** N/A

**Level of Certification:** LSA Repairman Maintenance or A&P